


EOD Improvements Effective April 2005

Positioning tabs for proper height at installation

Was...



Now...



Center-section to hinge tube alignment at mount plate refined to allow further rotation of unit

Was...



Now...



Linkage rod lug on front lip repositioned at customers suggestion reducing overloading of spring

Was...



Now...



Was...



Now...





9201 South Freeway – Fort Worth, TX 76140

(800) 433-2212 – (817) 293-7570 fax

Latch design refined at the suggestion of Chris Pinyan (Weld leadman) to prevent premature kick-off of the latch from the latch catch

Was...



Now...



Service You Can Stand On