



## Spring-Loaded Aluminum Dock Plate Installation Instructions

Model SL



1. Position the mount plates on surface of dock as shown in photo below.
  - a. Rotate springs so that the bent spring leg contacts underside of dock plate.
  - b. With SL plate in an upright position, compress the straight spring legs against the dock surface to allow the mount plates to rest on the dock surface in desired location.
  - c. To determine the mounting location, make certain the front lip will extended fully toward the truck and lay into the truck bed approximately 5" to 8". Also make sure the overhead dock door will close without contacting mount plates.
1. Once mounting location is obtained, drill holes for 1/2" wedge anchors utilizing a 1/2" concrete drill bit.
2. Secure unit in position using 1/2" x 4" concrete wedge anchors.
3. If the optional kick plates are used, attach the kick plates using these same anchors.
4. Once all the mount bolts have been tightened, raise the SL plate and adjust the stop bolts to desired upright stored position.

